
10
60
50
70
20
40
Process Controller 80
Tool 30
40
Process Controller 80
Tool 30
40
Tool 30
100
Rework Controller 90

Figure 1


300
Process a plurality of workpieces in a tool
310
Monitor a rework rate associated with the workpieces processed in the tool
320
Initiate an automatic corrective action in response to the rework rate being greater than a predetermined threshold

Figure 2